

Construction and Storm Water Inspection

April 3, 2019

Operator: BURLINGTON RESOURCES OIL & GAS LP – 26580

Location ID: 461862

Inspection Document #: 674902705

Arapahoe County, CO

NESE Section 29 T3S R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/3S64W29

Location ID: 461862



Photo 1. Photo taken from the entrance of the location off Imboden Road , facing West. Appears Operator has installed gravel to potentially limit tracking onto the road.



Photo 2. Photo taken from the entrance of the location off Imboden Road looking along the existing access road, facing East.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/3S64W29

Location ID: 461862



Photo 3. Photo taken from the access road looking into the location, facing North. Photo depicts the access road into the pad is currently under construction.



Photo 4. Photo taken from the access road, facing South. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/3S64W29

Location ID: 461862



Photo 5. Photo taken from the southeastern perimeter of the location, facing North. Photo illustrates a filtrex BMP that has been installed around the entire perimeter of the location in conjunction with other BMPs.



Photo 6. Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 5.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/3S64W29

Location ID: 461862



Photo 7. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 5.



Photo 8. Photo taken from the northeastern perimeter of the location, facing East. See comments from Photo 5.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/3S64W29

Location ID: 461862



Photo 9. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 5.



Photo 10. Photo taken from the northwestern perimeter of the location, facing South. Photo depicts the topsoil stock pile that is currently being salvaged.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP/3S64W29

Location ID: 461862



Photo 11. Photo taken from the northeastern perimeter of the location, facing North. See comments from Photo 5.



Photo 12. Photo taken from the northeastern perimeter of the location, facing South. See comments from Photo 5.