

Inspection Photos
Operator: BP America
Location/API #: 067-08293
Date: 4-9-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward.



Photo 3. View of musk thistle rosettes within the project area.



Photo 4. View of erosional tunneling within the eastern project area. Cobble BMP is not and adequate sto



Photo 5. View of more erosional tunneling within the eastern project area.