

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

678302440

FIELD INSPECTION FORM

Loc ID 431932 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Anadarko		COGCCinspections@Anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431929	WELL	PR	11/01/2018	OW	123-36870	THOMSEN 36C-18HZ	EI
431930	WELL	PR	11/01/2018	OW	123-36871	THOMSEN 13C-18HZ	EI
431931	WELL	PR	11/01/2018	OW	123-36872	THOMSEN 36N-18HZ	EI
431933	WELL	PR	11/01/2018	OW	123-36873	THOMSEN 14N-18HZ	EI
439755	WELL	PR	12/01/2018	OW	123-40547	THOMSEN 2N-31HZ	EI
439757	WELL	PR	11/01/2018	OW	123-40548	THOMSEN 5N-31HZ	EI
439775	WELL	PR	11/01/2018	OW	123-40555	THOMSEN 4N-31HZ	EI
440334	SPILL OR RELEASE	CL	11/28/2014		-	SPILL/RELEASE POINT	EI

General Comment:

production facilities not co-located with wells and battery not inspected in this report.

LocationOverall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:	WCW 4610C combined product (mostly CH3OH with other compounds) Unused CH3OH drums also labeled as to former contents, Drums appear empty		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	see attached photos of empty methanol drums inside fencing. 2 drums at 36N-18HZ and 1 drum at 13C-16HZ see photos attached		
Corrective Action:	Comply with Rule 603.f .	Date:	05/18/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: spill 440334 reported in 2014 at wellhead of 2N-31HZ No indications at surface of impacts from water based mud spill in 2014. spill closed in 2014 based on data submitted by form 19 process.

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 7		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1		STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: <u>431929</u>	Type: <u>WELL</u>	API Number: <u>123-36870</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431930</u>	Type: <u>WELL</u>	API Number: <u>123-36871</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431931</u>	Type: <u>WELL</u>	API Number: <u>123-36872</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>431933</u>	Type: <u>WELL</u>	API Number: <u>123-36873</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>439755</u>	Type: <u>WELL</u>	API Number: <u>123-40547</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>439757</u>	Type: <u>WELL</u>	API Number: <u>123-40548</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>439775</u>	Type: <u>WELL</u>	API Number: <u>123-40555</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>440334</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678302441	unused drums	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800272
678302442	unused drum	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800273