

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2019

Submitted Date:

04/18/2019

Document Number:

679703772**FIELD INSPECTION FORM**Loc ID 316020 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231931	WELL	PR	09/07/1993	GW	103-09602	DRAGON TRAIL UNIT 1150	PR
266563	WELL	PA	09/04/2007	GW	103-10280	DTU 1160	PA

General Comment:COGCC Inspection Report Summary.On 4/17/2019 at approximately 12:00, I, inspector Rick Moran, conducted a follow up inspection at Utah Oil & Gas well Dragon Trail Unit 1050 in Rio Blanco county.While there I conducted a follow up inspection of FIR document 679702827 along with a routine well inspection.During this inspection the following possible compliance issues were observed.

- 1) The tank secondary containment liner is torn.
- 2) Trash that ran off from location through a breached berm.
- 3) Storm water run off from location through a breached berm.
- 4) Soil scour on southeast hillside of location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.This is a summary of inspection report 679703772.

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-693-6021

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Plastic pipe end caps 5' to 30' northwest of location in breached berm channels.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/30/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		39.861690,-108.856580
Comment:	Pond located 340' northwest of tank.				

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal				Inadequate	
Comment:	Inadequate berms around tanks(s). Liner is degraded.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date:	03/08/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 231931 Type: WELL API Number: 103-09602 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on plunger lift.Corrective Action: Date: Facility ID: 266563 Type: WELL API Number: 103-10280 Status: PA Insp. Status: PA**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: P&A marker on location.Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: Location soil run off identified on the southwest to northwest side through breaches in the berm along the edge of the location.

Soil scour on the southeast hillside of the location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/20/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703773	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800275