

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Location sign. Sign not legible		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 05/11/2019
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around HYD motor skid		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907		Date: 05/11/2019
Type	OTHER		
Comment:	Stained soil under drain line for separator		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907.		Date: 05/11/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Vertical Separator	#		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	Braden head appears to be plumbed to surface		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas powered HYD motor		
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Guy line anchors not marked		

Corrective Action:	Install proper guy line markers per Rule 1003.a		Date:	05/02/2019
Type: Progressive Cavity	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 283710 Type: WELL API Number: 071-08734 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday April 11, 2019 at approximately 1735 hrs. I Randy Silver conducted an on-site inspection at a Timber Creek site GE #20-03, at API # 05-071-08734 in Las Animas County Colorado. While there, I observed a production well site. During this inspection the following possible compliance issues were observed: Un legible and faded location sign: Rule 210 e Corrective action date of 5-11-19 See photo 1 Stained soil Rule 907 e Corrective action date of 5-11-19 See photo 2 Stained soil; Rule 907 Corrective action date of 5-11-19 See photos 4,5 Guy line anchors; Rule 1003 a Corrective action date of 5-2-19 See photos 7,8 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/11/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402005794	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792675
688401832	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4792650