

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2019

Submitted Date:

04/10/2019

Document Number:

696300109

FIELD INSPECTION FORM

Loc ID 333033 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
16 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10110
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
 Address: 1001 17TH STREET #2000
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287398	WELL	TA	01/31/2018	OW	123-24312	GREAT WESTERN 27-13	TA
287400	WELL	SI	11/01/2018	OW	123-24313	GREAT WESTERN 27-14	PR
287403	WELL	SI	02/01/2018	OW	123-24315	GREAT WESTERN 27-24	PR
287404	WELL	SI	03/01/2017	OW	123-24316	GREAT WESTERN 27-53	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris from near by trees, bark inside tank berm, see photo #5		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Type	OTHER		
Comment:	Stained Soil by loadline bucket and southside on the loadline, see photos #3 and #4		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	05/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Old wellhead pipes and valves laying next to wellheads, see photos #6, 7,8, & 9		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Remove water hose on the outside of Tank Berm, see photo #2		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Type	TRASH		
Comment:	Trash southwest of ECD. Photo #1		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink around all 4 wellheads		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	150 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares same berm with Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.453820,-104.887470

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 287398 Type: WELL API Number: 123-24312 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

Facility ID: 287400 Type: WELL API Number: 123-24313 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 287403 Type: WELL API Number: 123-24315 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

Facility ID: 287404 Type: WELL API Number: 123-24316 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>On 04/10/2019, I Erica Petrie performed an inspection of the Great Western 8 Pad, Wellheads and Tank Battery (Location ID 333033), owned and operated by Great Western Operating Company LLC. Weather Conditions: Clear, dry and sunny.</p> <p>While on inspection I observed the following issue(s) Wellheads Great Western 27-13, 14, 24 and 54 has unused wellhead parts, see photos #6, 7, 8 & 9, Cite rule 210.b Trash on southwest corner of location by the ECD and separator, photo #1, Cite rule 603.f Unused equipment on the outside berm of Crude Oil tanks, see photo #2, Cite rule 210.b Stained soil by the loadline bucket and loadline, see photo #3 and #4, Cite rule 907.e Debris on the inside on the Crude Oil berm, see photo #5, Cite rule 210.b</p> <p>Continuing Education Inspection. END.</p>	petrie	04/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402007083	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793806
696300113	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793798