

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2019

Submitted Date:

04/12/2019

Document Number:

696300110

FIELD INSPECTION FORM

Loc ID 333026 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

- 18 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286095	WELL	SI	02/01/2018	GW	123-24123	GREAT WESTERN 27-54	SI
286701	WELL	TA	01/31/2018	GW	123-27277	GREAT WESTERN 27-43	TA
286702	WELL	SI	02/01/2018	GW	123-27276	GREAT WESTERN 27-44	SI
287296	WELL	TA	01/31/2018	GW	123-24286	GREAT WESTERN 27-33	TA
287297	WELL	SI	02/01/2018	GW	123-24285	GREAT WESTERN 27-34	SI

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	All 5 wellhead signs need to have Emergency Contact Info visible. 27-54, 27-34 sign are on the ground.		
Corrective Action:	Install sign to comply with Rule 210.b. See photos.	Date:	05/13/2019
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained Soil from leaking Casing collar on Well 27-33, See Photos #5		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	05/13/2019
Type	OTHER		
Comment:	Stained Soil by crude oil tanks from leaking loadline. See Photos #2		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	05/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused wellhead parts at all 5 wells, 27-33, 34, 43, 44, & 54, see photos #6, 9, 11, 13, & 15		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Type	UNUSED EQUIPMENT		
Comment:	Unmarked 1" risers. All 5 wellheads have a 1" unmarked riser, see photos #7,9, 11, 13, & 15		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Type	WEEDS		
Comment:	Weeds/grass inside Tank berm, see photos #3		
Corrective Action:	Comply with Rule 603.f .	Date:	05/13/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	SEPARATOR		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chainlink		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation Equipment		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	150
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: Shares berm with Crude Oil Tanks							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	3	300 BBLs	STEEL AST		40.454550,-104.874930		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 286095 Type: WELL API Number: 123-24123 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

Facility ID: 286701 Type: WELL API Number: 123-27277 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

Facility ID: 286702 Type: WELL API Number: 123-27276 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 287296 Type: WELL API Number: 123-24286 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

Facility ID: 287297 Type: WELL API Number: 123-24285 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>On 04/10/2019, I Erica Petrie performed an inspection of the Great Western 6 Pad, Wellheads and Tank Battery (Location ID 333026), owned and operated by Great Western Operating Company LLC. Weather Conditions: Clear, dry and sunny. While on inspection I observed the following issue(s): Stained soil from the loadline, appears to be leaking from hammer union, see photo #2, Cite rule 907.e Weeds inside the Crude Oil tanks berm, see photo #3 Unmarked 1" and 2" risers on wells 27-33, 43, 54. Unmarked 1" risers on 27-34, 44, see photos #7, 9, 11, 13, & 15, Cite rule 603.f Wellheads Great Western 27-33, 34, 43, 44 and 54 has unused wellhead parts, see photos #6, 8, 9 11 13, & 15, Cite rule 210.b Stained soil on Well 27-33, appears to be from leaking Casing Collar, see photo #5, Cite rule 907.e Continuing Education Inspection. END.</p>	petrie	04/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402007084	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793807
696300115	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4793799