

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2019

Submitted Date:

04/19/2019

Document Number:

690101168

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Oakman, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Porter, Phillip		Phillip.Porter@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463140	SPILL OR RELEASE	AC	03/26/2019		-	BJB 3	EG

General Comment:

COGCC follow up inspection (EG) performed on 4/18/19. The Corrective Actions Required outlined on FIR Doc #690101110 submitted on 03/12/2019 have been completed. Details are outlined in the flowline and comment sections of this report. Photos Uploaded.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: Pipe and debris have been removed at meter run.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 463140 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: _____ Material: Carbon Steel
 Variance: _____ Age: 15-20 Yrs Contents: Multiphase

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Corrective Action Completed; Flowline abandonments completed per COGCC rule 1105. COGCC FIRR Doc #401999043 has been approved/ passed.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>Note: There is (1) disconnected/ out of service gas gathering riser and meter run approximately 700' NE of the spill release point/ 950' NE of the (PA) wellhead:</p> <p>The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.</p>	maclarej	04/19/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101169	Signage at access to facility (decommissioned)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800639
690101170	Out of service meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800640
690101171	Remediation area/ surface recontoured	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800641