

Location

Overall Good:

Signs/Marker:

Type	OTHER			
Comment:	Location			
Corrective Action:			Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER				
Comment:	Mechanical issue; Packing appears to be leaking on well head and appears to be being drained with hose onto ground.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date:	04/13/2019
Type	OTHER				
Comment:	Stained soil around HR33-06V and both HYD motor skids.				
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A			Date:	05/12/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type				
Comment:				
Corrective Action:			Date:	

Equipment:

Type: Other	#			corrective date
Comment:	Braden head appears to be plumbed to surface.			
Corrective Action:			Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				

Corrective Action:

Date:

Inspected Facilities

Facility ID: 263769 Type: WELL API Number: 071-07637 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 272336 Type: WELL API Number: 071-08066 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday April 12, 2019 at approximately 1409 hrs. I Randy Silver conducted a follow up on-site inspection Doc#68790330 at a Timber Creek site, HR#33-06V and HR#33-06-02 at API# 05-071-07637 in Las Animas County Colorado. While there, I observed a producing well site During this inspection the following possible compliance issues were observed: Mechanical Issue; Rule 605 d Corrective action date of 4-13-19 See Photo 4 Stained soil; Rule 907 A Corrective action date of 5-12-19 See photos 5,6 At time of inspection all corrective actions from previous inspection have been addressed. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	04/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402007403	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794102
688401864	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4794088