

*Inspection Photos*  
*Loc#414268*  
*Operator: Laramie*  
*Insp#692400911*  
*Inspection Date: 4/16/2019*






**Photo#1:**  
Overview of Location from entry to Southeast.

April 16, 2019



Photo#2:  
Stormwater is collecting at points just off  
Pad.

April 16, 2019



Photo#3:  
Stormwater is collecting at points just off  
pad.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Knox Loc#414268





Photo#4:  
Stormwater cutting channels, washing out  
vegetation.

April 16, 2019



Photo#5:  
Stormwater cutting channels, washing out  
vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Knox Loc#414268





Photo#6:  
Sediment moving off site.

April 16, 2019



Photo#7:  
Sediment moving off site.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Knox Loc#414268



Photo#8:  
Erosion concerns on cut slope.

April 16, 2019



Photo#9:  
Erosion concerns on cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Knox Loc#414268