

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/15/2019

Submitted Date:

04/15/2019

Document Number:

696100764

FIELD INSPECTION FORM
 Loc ID 332433 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------|--------------------|
| Watt, Dustin | | dwatt@hpres.com | Sr. EHS Specialist |
| Barber, Matt | | mbarber@hpres.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 272939 | WELL | PR | 11/01/2018 | GW | 123-22293 | 70 RANCH LAURA 34-20 | PR |

General Comment:

This is a WELL Inspection.

Centralized Battery serves 3 Location IDs (332409, 332433, 332694). (1-well: PR, 1-well: PR, 3-wells: PR).

Refer to FIR #696100760 and/or Location ID #332409 for Battery / Facility, Equipment info.

| Location | | | |
|--|---|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | Trash at wellsite. Remove trash at wellsite (rag). Refer to Rule 603.f (10 Days). See photo #1. | | |
| Corrective Action: | Remove trash at wellsite (rag). See photo #1. Comply with Rule 603.f. | | Date: 04/25/2019 |
| Type | WEEDS | | |
| Comment: | Weed encroachment at wellsite. Remove, manage, & control weeds around wellsite. Refer to Rule 603.f (10 Days). See photo #1. | | |
| Corrective Action: | Remove, manage, & control weeds around wellsite. See photo #1. Comply with Rule 603.f. | | Date: 04/25/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | Refer to FIR #696100760 and/or Location ID #332409 for additional Fencing info. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Iron panel | | |
| Corrective Action: | | | Date: |

| | | | | |
|--------------------|---|--|--|-----------------|
| Equipment: | | | | corrective date |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: | # | | | |
| Comment: | Refer to FIR #696100760 and/or Location ID #332409 for additional Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Type: Other | # 1 | | | |
| Comment: | Bradenhead appears plumbed to surface. | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|---------------------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| | | | CENTRALIZED BATTERY | | 40.384360,-104.465870 | |
| Comment: | Centralized Battery serves 3 Location IDs (332409, 332433, 332694). Refer to FIR #696100760 and/or Location ID #332409 for Tanks & Berms info. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 272939 | Type: | WELL | API Number: | 123-22293 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary: On MON APR 15, 2019 at approximately 13:34 hrs. I, Bret Evins, conducted an on-site inspection at: Facility ID #332433, 70 RANCH LAURA-65N63W /20SWSE Operated by HighPoint Resources. While there I observed: Well(s) - 1: Producing. Centralized Battery serves 3 Location IDs (332409, 332433, 332694). (1-well: PR, 1-well: PR, 3-wells: PR). Refer to FIR #696100760 and/or Location ID #332409 for Battery / Facility, Equipment info. 2 - Corrective Actions observed. Prior Corrective Actions date remains applicable. 1.) Weed encroachment at wellsite. Remove, manage, & control weeds around wellsite. Refer to Rule 603.f (10 Days). See photo #1. Comply with Rule 603.f. Corrective Action date: 04/25/2019. 2.) Trash at wellsite. Remove trash at wellsite (rag). Refer to Rule 603.f (10 Days). See photo #1. Comply with Rule 603.f. Corrective Action date: 04/25/2019.</p> <p>This is a summary of the inspection report.</p> | evinsb | 04/15/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402009536 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4796052 |
| 696100765 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4796050 |