

Inspection Photos
Loc#457122
Operator: Caerus
Insp#692400904
Inspection Date: 4/15/2019





Photo#1:
Overview of Location from top of Cut slope to Southwest.

April 15, 2019



Photo#2:
View along Southern perimeter of Location.

April 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR P17 Loc#457122



Photo#3:

Southwest of entry showing a more defined compacted definition between fill slope & topsoil than further South along the perimeter.

April 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR P17 Loc#457122



Photo#4:
Topsoil windrowed along toe of Fill slope

April 15, 2019



Photo#5:
Topsoil windrowed along toe of Fill slope



Photo#6:
Topsoil windrowed along toe of Fill slope

February 28, 2018



Photo#7:
Wattles have been installed as Perimeter control.

February 28, 2018



Photo#8:
In a few places wattles have been overwhelmed.