

Penrose #2-8H

Corrective Actions Taken on the Penrose #2-8H for the COGCC
compliance INC.

Penrose #2-8H

04/22/19



Interim reclamation has been conducted and Storm Water management controls have been established to stabilize erosion. Location tear drop has been established, top soil has been laid out, and all disturbed area's have been seeded with the exception of the tear drop driving surfaces.



Interim reclamation has been conducted and Storm Water management controls have been established to stabilize erosion.



View of storm water controls and reclamation looking south on east side of location.



View of storm water controls and reclamation to location entrance looking North on east side of location.



View of storm water controls and reclamation southwest corner of location.



View of storm water controls and reclamation looking southeast.



View of storm water controls and reclamation looking north on southeast corner of location.



View of storm water controls and reclamation looking east.

Storm Water management controls have been established to stabilize erosion water run on from adjacent location.



View of storm water controls looking north to adjacent 067-08698 well pad.