

Construction and Stormwater Inspection

April 2, 2019

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 461838

Inspection Document #: 697500009

Weld County, CO

NWNW Section 33 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Colorado Rivers Pad
Location ID: 461838



Photo 1. Photo taken from the eastern well location, facing South. Photo illustrates a ditch installed around the perimeter of the well pad which will be directed to a sediment trap. The eastern fill slope has been temporarily stabilized with equipment tracking.



Photo 2. Photo taken from the southeastern location, facing Northwest. Operator is still in process of constructing the location. The southern fill slope needs to be stabilized and will be tracked in like the eastern fill slope.

Inspection Photos
Location Name: Colorado Rivers Pad
Location ID: 461838



Photo 3. Photo taken from the western location, facing North. Photo illustrates a portion of the topsoil stockpile. Operator shall comply with Rule 1002 to stabilize the topsoil stockpile.



Photo 4. Photo taken from the northwestern location, facing West. Operator shall stabilize the berm BMP, as an unconsolidated berm BMP is not a properly functioning BMP.