

Inspection Photos
Location Name: Federal 43-20
API: 05-081-07197



Photo 1. Overview of location taken at entrance facing west.



Photo 2. Non reportable spill. Stained soil at meter run flowline.