

# Inspection Photos

4/24/2019

Operator: BENCHMARK ENERGY LLC - 10380

Location ID: 390294

Inspection Doc. Number: 682504795

Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: BENCHMARK ENERGY LLC - 10380  
Location ID: 390294



**Photo 1:** Photo taken from the southwest end of the tank battery, facing north. Photo shows weed debris accumulation on the berms and around equipment.



**Photo 2:** Photo taken from the southwest end of the tank battery, facing east. Photo shows weed debris accumulation on the berms and around equipment.

Inspection Photos  
Operator: BENCHMARK ENERGY LLC - 10380  
Location ID: 390294



**Photo 3:** Photo taken from berm at the tank battery, facing north. Photo shows weed germination and weed debris accumulation on the berms and around equipment.



**Photo 4:** Photo taken from the south of the tank battery, facing north. Photo shows large areas of the location where undesirable weedy plant species appear to be the only vegetation establishing.

Inspection Photos  
Operator: BENCHMARK ENERGY LLC - 10380  
Location ID: 390294



**Photo 5:** Photo shows undesirable weedy plant establishment, and weed debris accumulation on berms and equipment.



**Photo 6:** Photo shows undesirable weedy plant establishment, and weed debris accumulation on berms and equipment.

Inspection Photos  
Operator: BENCHMARK ENERGY LLC - 10380  
Location ID: 390294



**Photo 7:** Photo shows undesirable weedy plant establishment, and weed debris accumulation on berms and equipment.



**Photo 8:** Photo shows undesirable weedy plant establishment, and weed debris accumulation on berms and equipment.