

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2019

Submitted Date:

04/24/2019

Document Number:

679703844**FIELD INSPECTION FORM**
 Loc ID 398807 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment                         |
|-----------------|--------------|----------------------------|---------------------------------|
| Trujillo, Helen |              | notices@rlbayless.com      | <a href="#">All inspections</a> |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 277804      | WELL | PR     | 04/15/2009  | GW         | 103-10580 | WEAVER RIDGE 13-9   | PR          |
| 418872      | WELL | PR     | 08/09/2012  | OW         | 103-11781 | Weaver Ridge 13-9 H | PR          |
| 418876      | WELL | PR     | 01/27/2011  | GW         | 103-11782 | Weaver Ridge 13-16  | PR          |

**General Comment:**

COGCC Inspection Report Summary.

On 4/24/2019 at approximately 7:45, inspector Rick Moran, conducted a follow up inspection at Robert L Bayless well Weaver Ridge 13-9 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679702652. The well inspection was limited due to a rig on location. Equipment located within the guide wires of the rig was not inspected.

During this inspection the following corrective action was identified as resolved:

- 1) The tank capacity labels.

Corrective actions not completed:

- 1) Removal of partially melted lead batteries.

Undetermine if corrective actions were completed due to the rig on location:

- 1) Two containers without labels.
- 2) Missing well head sign for well 13-9.

During this inspection the following possible compliance issues were observed:

- 1) Gas leaking at the separator.
- 2) Open buckets of fluid next to separator.
- 3) Oily stained soil near pump jack motor.
- 4) Open container of fluid over flowing with oily stained soild next to separator.
- 5) Unmarked deadman.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703844.

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |              |  |             |
|---------------------------|--------------|--|-------------|
| Emergency Contact Number: |              |  |             |
| Comment:                  | 505-327-0880 |  |             |
| Corrective Action:        |              |  | Date: _____ |

|                           |  |  |                  |
|---------------------------|--|--|------------------|
| <b>Good Housekeeping:</b> |  |  |                  |
| Type                      | OTHER  |  |                  |
| Comment:                  | Oily stained soil next to separator with open container of fluid over flowing unto the ground. |  |                  |
| Corrective Action:        | Properly treat or dispose of oily waste in accordance with 907.e.                              |  | Date: 05/24/2019 |
| Type                      | OTHER  |  |                  |
| Comment:                  | Open buckets with unknown fluid stored in secondary containment next to separator.             |  |                  |
| Corrective Action:        | Comply with Rule 603.f .   |  | Date: 05/08/2019 |
| Type                      | OTHER  |  |                  |
| Comment:                  | Oily stained soil next to pump jack.   |  |                  |
| Corrective Action:        | Properly treat or dispose of oily waste in accordance with 907.e.                              |  | Date: 05/24/2019 |
| Type                      | TRASH  |  |                  |
| Comment:                  | Partially melted lead batteries on location.   |  |                  |
| Corrective Action:        | Comply with Rule 603.f.  |  | Date: 02/15/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                                   |   |  |                  |
|-----------------------------------|---|--|------------------|
| <b>Equipment:</b>                 |   |  | corrective date  |
| Type: Deadman # & Marked          | #   |  |                  |
| Comment:                          | One guy line anchor not marked at lease road entrance.  |  |                  |
| Corrective Action:                | Install proper guy line markers per Rule 1003.a   |  | Date: 05/10/2019 |
| Type: Horizontal Heated Separator | #   |  |                  |
| Comment:                          | Separator leaking gas.  |  |                  |
| Corrective Action:                | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. |  | Date: 05/24/2019 |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |
|--|
|  |
|--|

| Inspected Facilities  |  |       |      |             |           |         |       |               |    |
|-----------------------|--|-------|------|-------------|-----------|---------|-------|---------------|----|
| Facility ID:          | 277804   | Type: | WELL | API Number: | 103-10580 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |         |       |               |    |
| Comment:              | All wells idle at time of inspection. Rig on one well. |       |      |             |           |         |       |               |    |
| Corrective Action:    |  |       |      |             |           |         | Date: |               |    |
|                       |  |       |      |             |           |         |       |               |    |
| Facility ID:          | 418872   | Type: | WELL | API Number: | 103-11781 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |         |       |               |    |
| Comment:              | All wells idle at time of inspection. Rig on one well. |       |      |             |           |         |       |               |    |
| Corrective Action:    |  |       |      |             |           |         | Date: |               |    |
|                       |  |       |      |             |           |         |       |               |    |
| Facility ID:          | 418876   | Type: | WELL | API Number: | 103-11782 | Status: | PR    | Insp. Status: | PR |
| <b>Producing Well</b> |  |       |      |             |           |         |       |               |    |
| Comment:              | All wells idle at time of inspection. Rig on one well. |       |      |             |           |         |       |               |    |
| Corrective Action:    |  |       |      |             |           |         | Date: |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

|         |             |            |                 |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
|         | 419282      | 2521254    |                 |
|         | 419282      | 2521254    |                 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 679703845    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805464">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4805464</a> |