

Inspection Photos
Location Name: MURPHY 21-20
API #: 05-071-06356
Insp. Doc. # 695100540



Colorado Oil & Gas Conservation Commission
37.16302, -104.69816, 2084.0m, 158°
2019/04/24 15:16:50



Colorado Oil & Gas Conservation Commission
37.16283, -104.69835, 2088.0m, 226°
2019/04/24 15:17:57

PHOTO 1: LOCATION

PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: MURPHY 21-20
API #: 05-071-06356
Insp. Doc. # 695100540



PHOTO 3: THERE IS IMPACTED SOIL ON SOUTH AND SOUTHWEST SIDE OF COMPRESSOR POWER UNIT SKID

PHOTO 4: THERE IS APPROXIMATELY 2" OF OILY WATER IN COMPRESSOR POWER UNIT SKID.

Inspection Photos
Location Name: MURPHY 21-20
API #: 05-071-06356
Insp. Doc. # 695100540



PHOTO 5: INADIQUATE VEGETATION COVER ON WEST SIDE OF LOCATION

PHOTO 6: INADIQUATE VEGETATION COVER ON DISTERBED AREA ON WEST SIDE OF LOCATION NEAR METER HOUSE

Inspection Photos

Location Name: MURPHY 21-20

API #: 05-071-06356

Insp. Doc. # 695100540



**PHOTO 5: INADIQUATE VEGETATION COVER ON WEST SIDE
OF LOCATION**

