

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/17/2019

Submitted Date:

04/18/2019

Document Number:

679703770**FIELD INSPECTION FORM**

Loc ID 315922	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10539</u> Name of Operator: <u>UTAH GAS OP LTD DBA UTAH GAS CORP</u> Address: <u>1125 ESCALANTE DR</u> City: <u>RANGELY</u> State: <u>CO</u> Zip: <u>81648</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231763	WELL	PR	09/27/1990	GW	103-09434	DRAGON TRAIL UNIT 1075	PR

General Comment:[COGCC Inspection Report Summary.](#)

On 4/17/2019 at approximately 11:00, I, inspector Rick Moran, conducted a follow up inspection at Utah Oil & Gas well Dragon Trail Unit 1075 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679702825 along with a routine well inspection.

During this inspection the following possible compliance issues were observed.

- 1) The tank secondary containment liner is torn.
- 2) Debris from the tank liner has blown off location.
- 3) Storm water run on to location.
- 4) Tracking off location.
- 5) "911" missing on the battery sign.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679703770.

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. "911" missing in sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	06/17/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-693-6021

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Tank liner pieces blow off location.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/20/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	<50 BBLs	Open Top		39.865530,-108.854940	
Comment: Tank is located 120' east of a seasonal stream.						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 30 bbl						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal				Inadequate		
Comment: Inadequate berms around tank(s). Liner is degraded.						
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).					Date:	03/08/2019
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities			
Facility ID: 231763	Type: WELL	API Number: 103-09434	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Producing well on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: Storm water running unto the southeast corner of the location through a breached berm.

Vehicle tracking of dirt from the location unto the BLM dirt lease road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/20/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402014419	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800281
679703771	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800274