

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Plunger Lift	# 1				corrective date
Comment:					
Corrective Action:		Date:			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 275619 Type: WELL API Number: 123-22645 Status: PR Insp. Status: PR**COGCC Comments**

Comment	User	Date
<p>On Thursday, April 25, 2019 at 14:05, I, Craig Carlile conducted an on-site inspection at: 332688, WARDELL-63N65W 7SWNE Operated by: Crestone While there I observed: Well(s) Producing Possible compliance issues observed: No: ? Routine Inspection. This is a summary of the inspection report.</p>	carlilec	04/25/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003443	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806755