



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Emission Control Device

# 0

corrective date

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

# 0

Comment:

Corrective Action:

Date:

Type: Pump Jack

# 0

Comment: [At time of inspection location appears to be P&A, and reclaimed.](#)

Corrective Action:

Date:

Type: Gas Meter Run

# 0

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 0

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 202532 Type: WELL API Number: 001-07937 Status: SI Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
At time of inspection Location appears to be in compliance with COGCC rules. This is a follow up inspection from Document # 688400504 Continuing Education Inspection.	medinaj	04/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100817	Loc Pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806881">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806881</a>