

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2019

Submitted Date:

04/25/2019

Document Number:

690101183

FIELD INSPECTION FORM

Loc ID 320352 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1001 17TH STREET #2000
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203526	WELL	TA	02/08/2019	OW	001-09086	WIERMAN 43-7 (1)	EG
441104	SPILL OR RELEASE	CL	02/13/2015		-	SPILL/RELEASE POINT	EG

General Comment:

Engineering Integrity inspection performed on April 24th, 2019 in response to initial form 19 spill report Doc #402016639 received by COGCC on 04/22/2019 that outlines: Potential soil and groundwater impacts were discovered at the tank battery during abandonment activities. Details of observations made during this field inspection are located in the flowline section of this report. Photos uploaded.

Inspected Facilities			
Facility ID: <u>203526</u>	Type: <u>WELL</u>	API Number: <u>001-09086</u>	Status: <u>TA</u> Insp. Status: <u>EG</u>
Flowline			
#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
Comment:	Well has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #401945944 received on 02/20/2019. The wellhead flowline has been removed, no risers present. Dump flowlines, tanks and equipment at facility/ battery are in process of being removed. Excavation and remediation activities pertaining to historical impacts identified are in progress. No Great Western or contract personnel were on location at the time of this field inspection.		
Corrective Action:			Date:
Facility ID: <u>441104</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u> Insp. Status: <u>EG</u>

COGCC Comments		
Comment	User	Date
COGCC Form 42 notice of flowlines abandoned Doc #402016063 received on 04/22/2019.	maclarej	04/25/2019
*Note: There is (1) disconnected/ out of service gas gathering riser and meter run on location:	maclarej	04/25/2019
The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101185	Signage at PA well; excavation and flowline removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806966
690101186	Gas meter run; Out of service	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806967
690101187	Production tank, equipment being removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4806968