

Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 1-Wellhead,looking northeast. It was observed that the spill blew primarily to the northwest. Note tank in background for reference.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 2-Wellhead is behind and to the left of camera, looking north . Note: treater in right center at the edge of pad for reference. Note pooling of oil in truck ruts.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 3-Looking north. Note pooling of oil on access road in truck ruts.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 4-Close up of wester most tank. Fluid on ground inside tank battery. Tank was estimated to be mostly empty, tank was not gauged or observed from the gauge hatch, This tank was bulged out as if it had been over pressurized. The fluid appeared to be weathered oil, there may be a seep from the tank.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 5- Area north of pad.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 6-Area north of obvious impacted area. Note: black temporary surface water impoundment. It was discovered from email with BLM that they had this installed to contain runoff from location. The area was dry at time of inspection. NO fluid was observed to be migrating out of initial spill area.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel



Photo 7-Looking southwest. Note: backhoe is parked perpendicular to the access road that crosses pad. Tank battery berm in foreground.



Inspection Photos

Location: Taiga Mt 6-22, API 103-08920

Inspection Date: 4/24/19

All Photos taken by COGCC staff Kris Neidel

ction

approximation of the area impacted by spill.



Photo 8-COGCC approximation of spill area and areas of pooling on pad. This document will be a separate attachment on inspection.

