

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2019

Submitted Date:

04/25/2019

Document Number:

688304465**FIELD INSPECTION FORM**Loc ID 320777 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204893	WELL	SI	02/01/2019	OW	005-06978	MURPHY 5-2	SI

General Comment:[Reinspection. Erosion at GMR was maintained, however, bomb cyclone storm created new rill that needs maintenance \(see attached photos\).](#)

Inspected FacilitiesFacility ID: 204893 Type: WELL API Number: 005-06978 Status: SI Insp. Status: SI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304509	KPK Murphy 5-2 TB sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4807152
688304510	KPK Murphy 5-2 new rill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4807153
688304511	KPK Murphy 5-2 new rill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4807154
688304512	KPK Murphy 5-2 new rill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4807155