

# Inspection Photos

API: 05-071-06678

Operator: Evergreen Natural Resources

Inspection Date: 4/24/2019

## Inspection Photos



**Photo 1.** Facing toward the wellhead. There is some vehicle rutting this area may need more gravel.

## Inspection Photos



**Photo 2.** Facing off the north fill slope. Berms and rock rip/rap are installed for stormwater control.

## Inspection Photos



**Photo 3.** The fill slope was mulched and seeded. Vegetation is beginning to establish.