

# Construction and Storm Water Inspection

April 25, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP – 47120

Location ID: 463802

Inspection Document #: 674902808

Weld County, CO

NENE Section 28 T3N R66W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 1.** Photo taken from the entrance of the location off CR 30, facing North. Appears the Operator is currently building the access road.



**Photo 2.** Photo taken from the southwestern perimeter of the location, facing North. Photo illustrates the ditch and berm BMP that has been installed around the perimeter of the location. However, parts of the ditch and berm BMP remain unconsolidated.



## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 3.** Photo taken from the northern perimeter of the location, facing East. See comments from Photo 2.



**Photo 4.** Photo taken from the southwestern perimeter of the location, facing West. See comments from Photo 2.

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 5.** Photo taken from the northern perimeter of the location, facing East. See comments from Photo 2.



**Photo 6.** Photo taken from the northeastern perimeter of the location, facing East. Appears the Operator is installing sediment traps with stabilized outlets around the location.



## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 7.** Photo taken from the northeastern perimeter of the location, facing South. See comments from Photos 2 and 6.



**Photo 8.** Photo taken from the northeastern perimeter of the location, facing West. See comments from Photos 2 and 6.

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 9.** Photo taken from the southeastern perimeter of the location, facing West. See comments form Photo 2.



**Photo 10.** Photo taken from the southeastern perimeter of the location, facing North. See comments form Photo 2.



## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 11.** Photo taken from the southern perimeter of the location, facing West. See comments from Photo 2.



**Photo 12.** Photo taken from the southern perimeter of the location, facing Northeast. See comments from Photo 2.

## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 13.** Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 2.



**Photo 14.** Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 2.



## Inspection Photos

Location Name: KERR MCGEE OIL & GAS ONSHORE LP/3N66W28

Location ID: 463802



**Photo 15.** Photo taken from the southern perimeter of the location, facing West. Photo depicts the Operator is currently salving top soil and is being stored at the western end of the location.



**Photo 16.** Photo taken from the northern perimeter of the location, facing South. See comments from Photo 15.