

# Inspection Photos

API: 05-071-08803

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/25/2019

## Inspection Photos



**Photo 1.** Facing toward the cut slope. This area appears to have been reseeded and stabilized with mulch. Diversion ditch has been cleaned out.



## Inspection Photos



**Photo 2.** Oil stained soil appears to have been removed.

## Inspection Photos



**Photo 3.** Well sign located at meter shed.



## Inspection Photos



**Photo 4.** Erosion issues along the fill slope have been fixed. A diversion ditch with EC blanket was installed.