

Inspection Photos

API: 05-071-09682

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/25/2019

Inspection Photos



Photo 1. Facing northeast at the location. Maintenance was being performed at the well engine during inspection.

Inspection Photos



Photo 2. Topsoil pile at the north side of the location appears to be stabilized.

Inspection Photos



Photo 3. There is an erosion channel that formed at the south fill slope.

Inspection Photos



Photo 4. Culverts appear to be properly installed and maintained.