

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2019

Submitted Date:

04/26/2019

Document Number:

688304461**FIELD INSPECTION FORM**
 Loc ID 316985 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Warner, Ross	720-309-9380	ross.magpieoil@gmail.com	<a href="#">All Inspections</a>
Warner, Ryan and James	(970) 669-6308	magpieoil@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234108	WELL	SI	10/01/2010		121-06207	LITTLE BEAVER UNIT 45	TA

**General Comment:**[MIT Inspection, passed](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 234108 Type: WELL API Number: 121-06207 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Magpie's water truck, well was full  
 Casing 0 psi before and after test, no bradenhead plumbed to surface  
 0 min 410 psi  
 5 min 405 psi  
 10 min 400 psi  
 15 min 400 psi  
 From 21 not attached, operator to submit it electronically.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304560	Magpie LBU 45	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808168</a>
688304561	Magpie LBU 45	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808169">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808169</a>