

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2019

Submitted Date:

04/26/2019

Document Number:

688304505**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 316996 Sherman, Susan 2A Doc Num: _____

Operator Information:OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Warner, Ryan and James	(970) 669-6308	magpieoil@yahoo.com	
Warner, Ross	720-309-9380	ross.magpieoil@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234168	WELL	SI	08/01/2017	ERIW	121-06269	LITTLE BEAVER UNIT 31	TA

General Comment:

[UIC MIT, passed](#)
[Check subsidence at wellhead](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Flow Line	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:						
Corrective Action:				Date:		

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected FacilitiesFacility ID: 234168 Type: WELL API Number: 121-06269 Status: SI Insp. Status: TA**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 07/11/2014

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: NA Csg psi: 0 BH psi: 0Insp. Status: Pass

Comment: Magpie water truck, ~1 bbl to load hole
 Casing 0 psi before and after test, Bradenhead dug up and dead
 0 min 400 psi
 5 min 400 psi
 10 min 400 psi
 15 min 400 psi
 No Form 21 is attached. Magpie has signed copy and is to submit electronically.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304562	Magpie LBU 31	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808170
688304563	Magpie LBU 31	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808171