

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2019

Submitted Date:

04/26/2019

Document Number:

687904682**FIELD INSPECTION FORM**Loc ID 334315 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Shorty, Priscilla		pshorty@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258539	WELL	PR	02/04/2003	GW	067-08361	FINNEY 4-12U	PR
286590	WELL	PR	10/14/2009	GW	067-09235	FINNEY 5-12U	PR

General Comment:[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	According to attached photo documents, Compressor had been removed prior to 6/14/2017. Flowlines for suction and discharge of compressor, and flowlines for produced water have been LOTO and are no longer in use so they are unused equipment that need to be removed.		
Corrective Action:	Comply with Rule 603.f.	Date:	07/26/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead with PVC bradenhead access.		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	MCC for electric motor on pumpjack.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Pigging station in corner of location.		
Corrective Action:		Date:	
Type: Flow Line	# 8		
Comment:	1-3" flowline from wellhead to separator. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. 1-2" flowline from separator dump valve to offsite produced water gathering system. 2-4" flowlines from wellhead to separator. 1-3" flowline from separator dump valve to offsite produced water gathering system. 1-4" flowline from separator to offsite dogleg.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Compressor building with suction and discharge flowline piping as well as Produced water flowline piping that is no longer in service.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 258539 Type: WELL API Number: 067-08361 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 286590 Type: WELL API Number: 067-09235 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904684	Unused flowlines suction/water	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808521
687904685	Unused flowlines discharge/water	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808522
687904686	Out of service date.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808523
687904687	Unused flowlines at separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808524
687904688	Location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4808525