

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2019

Submitted Date:

04/29/2019

Document Number:

682600663

**FIELD INSPECTION FORM**

Loc ID 308737 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergy.us	<a href="#">All Inspections</a>
Beardslee, Tom		tom.beardslee@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280077	WELL	PR	07/01/2011	GW	071-08542	APACHE CANYON 35-05	EI

**General Comment:**

This is a follow up inspection to COGCC Inspection 695100457 which found a possible spill from a seeping pit. Operator has collected soil samples from observed seep area and analytical results are forthcoming. Operator should send analytical results in via FIRR in response to this environmental inspection.

Operator states pit has only been used for 2.5 days around the time of the previous COGCC inspection of location. Operator is not currently producing water to pit. During inspection this inspector found that a seep still appeared on the downslope side of the pit. Pending analytical results it is believed that the seep is likely naturally occurring. Other corrective actions appear to have been completed.

**Inspected Facilities**

Facility ID: 280077 Type: WELL API Number: 071-08542 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600665	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809355">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4809355</a>