Inspector Name: Arauza, Steven

FORM INSP

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2019
Submitted Date:

04/29/2019
Document Number:

681701210

FIELD INSPECTION FORM

Loc ID Inspector Name:			On-Site Inspection			Status Summary:				
Arauza, Steven			2A	A Doc Num:			X	THIS IS A FOLLOW UP INSPECTION		
Operator Information:							FOLLOW UP INSPECTION REQUIRED			
OGCC Ope	rator Number:	10433					N	NO FOLLOW UP INSPECTION F	REQUIRED	
Name of Op	erator: LARAMIE	ENERGY	LLC				<u>Find</u>	ings:		
	_						5	Number of Comments		
Address: 1	401 SEVENTEEN	IHSIKEE	1 #1401				3 Number of Corrective Actions			
City:	DENVER	State:	CO	Z	ip: 80202	<u> </u>				
							ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE			
Contact Inf	ormation:									
Contact Na	ame	Phon	ie	Email				Comment		
Murray, Ri	chard		g.ric		g.richard.murray@state.co.us					
Prescott, Lorne		(970	970) 812-5311		lprescott@laramie- energy.com					
Fischer, Al	ex				alex.fischer@state.co.us					
Colby, Lou			lou.colby@			.co.us	us			
Bankert, Wayne					wbankert@laramie- energy.com					
, Laramie				cogccnotifications@laramie- energy.com		All Inspections				
Inspected F	acilities:									
Facility ID	Туре	Status	Status Date	V	Well Class API Num		Facility Name	Insp Status		
461292	SPILL OR RELEASE	CL	03/25/2019			-		HSC-5 Pipeline	EI	
General Co	mment:									
	nvironmental inspe spector R. Murray.					pection co	nducte	ed by COGCC EPS S. Arauza ar	nd Western	
	cavation related to een covered with o				had been bad	kfilled by	opera	tor prior to inspection date. Back	dilled excavation	
COGCC R	eclamation Specia	list, Lou C	olby, is include	ed as a	contact on th	nis Field Ir	spect	tion Report.		

Inspector Name: Arauza, Steven **Location** Overall Good: Emergency Contact Number: Comment: Corrective Action: Date: **Good Housekeeping:** TRASH Туре Comment: Trash and junk remain north of backfilled excavation area. See photos. Corrective Action: Comply with Rule 603.f. Date: 05/09/2019 Overall Good: Spills: Туре Area Volume In Containment: No Comment: Multilple Spills and Releases? Venting: Yes/No Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: Arauza, Steven

mopostor real	,			Inspected Facilities	<u>i</u>			
Facility ID:	461292	Type:	SPILL OR	API Number:	Status: _	CL	Insp. Status: _	EI

Inspector Name: Arauza, Steven

<u>Environmental</u>									
Spills/Releases:									
Type of Spill:		Estimated S	Spill Volume:						
Comment:	indicated that the flowline exc	estigation and Remediation We cavation would be backfilled pr lled excavation was covered w							
Corrective Action:		ed area in accordance with Collist Lou Colby to discuss recla			Date: 05/31/2019				
Reportable:		GPS: Lat	Long _						
Proximity to Surface	e Water:	Depth to Ground Water:							
Water Well Compl	aint:		Lat	Long					
DWR Receipt Num	: Owner Na	ame:	GPS:						
Field Parameters:									
Sample Location: Comment:									
Spill/Remediation	<u>.</u>								
	rator has not submitted update oved by the COGCC on 2/14/2		99 since the Initial eF	Form 27 (doc #4	01931784) was				
Action: com									
Emission Control B	urner (ECB):								
Comment:									
Pilot:	Wildlife Protection Dev	vices (fired vessels):			_				
Attached Docum	<u>nents</u>								
You can go to CC	OGCC Images (https://cogco	c.state.co.us/weblink/) and	search by docume	nt number:					
	Description	URL							
681701263	20190423 field photos http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=480973								