

Inspection Photos
Location Name: North York 13-12#3
Location ID: 320313



Photo 1 WH



Photo 2 sep/meter house and ECD. Location located in a flood plain equipment not properly anchored and inadequate berm.

Inspection Photos
Location Name: North York 13-12#3
Location ID: 320313



**Photo 3 TNK BTRY. Location located in a flood plain
equipment not properly anchored and inadequate berm.**



Photo 4 NFPA placard faded and illegible.

Inspection Photos
Location Name: North York 13-12#3
Location ID: 320313



Photo 5 TNK BTRY. Production tanks Location located in a flood plain equipment not properly anchored and inadequate berm.



Photo 6 Location is located in a flood plain.