

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2019

Submitted Date:

04/30/2019

Document Number:

685100864

FIELD INSPECTION FORM

Loc ID 318972 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 1099 18TH ST STE 2300
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Watt, Dustin		dwatt@hpres.com	Sr. EHS Specialist
Gomez, Jason		jason.gomez@state.co.us	
Barber, Matt		mbarber@hpres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242618	WELL	PR	09/01/2017	GW	123-10409	LUCY 14-26	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Vertical Separator	# 1				
		Comment:			
		Corrective Action:		Date:	
Gas Meter Run	# 1				
		Comment:			
		Corrective Action:		Date:	
Bradenhead	# 1				
		Comment: Plumbed to surface			
		Corrective Action:		Date:	
Horizontal Heated Separator	# 1				
		Comment:			
		Corrective Action:		Date:	
Type:	#				
		Comment:			
		Corrective Action:		Date:	
Plunger Lift	# 1				
		Comment:			
		Corrective Action:		Date:	
Bird Protectors	# 1				
		Comment:			
		Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.017190,-104.526690
		Comment:			
		Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		40.017190,-104.526690
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares containment with oil tank.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 242618 Type: WELL API Number: 123-10409 Status: PR Insp. Status: PR

Producing Well

Comment: At time of inspection wellhead appears to have bubbles coming out of wellhead. See pic 2,3,4.

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/01/2019

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment COGCC Inspection Report Summary On 4/30/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Lucy 14-26 Highpoint Operation Corp. at 123-10409 in Weld County Colorado. While there, I observed producing well. During this inspection the following possible compliance issues were observed: At time of inspection wellhead appears to have bubbles coming out of wellhead. See pic 2,3,4. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 5/1/2019 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection HP Res employee informed me that KPK will be taking over well in near future. This is a summary of inspection report. CEI	User medinaj	Date 04/30/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100865	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811052