

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2019

Submitted Date:

04/30/2019

Document Number:

685100868**FIELD INSPECTION FORM**
 Loc ID 319555 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------------|---------------------------------|
| Singer, Sheila | | ssinger@hpres.com | All Inspections |
| , KPK | | cogcc@kpk.com | All Inspections |
| Gomez, Jason | | jason.gomez@state.co.us | |
| Canfield, Chris | | chris.canfield@state.co.us | |
| Barber, Matt | | mbarber@hpres.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 243675 | WELL | PR | 03/01/2018 | GW | 123-11467 | LINDA 1 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Vertical Separator

1

Comment: What appears to be leak below seperator. Stained soil. see pic 6

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/30/2019

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 40.034500,-104.491710 |

Comment: What appears to be leak on oil tank. Stained soil. See pic 3 & 4.

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 05/30/2019

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |

| | | | | |
|-----------------------------|-------------------------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 243675 | Type: WELL | API Number: 123-11467 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Well appears to be producing. | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | Material Handling And Spill Prevention | Fail | |

Comment: [No containment under chemical barrel. Appears to be leaking stained soil. See pic 1 & 2](#)

Corrective Action: [Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.](#)

Date: 05/02/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On 4/30/19 at approximately 1200, Inspector Justin Medina conducted an on-site inspection at Linda #1 Highpoint Operation Corp. at 123-11467 in Weld County Colorado.</p> <p>While there, I observed producing well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>What appears to be leak below separator. Stained soil. see pic 6</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 5/30/19</p> <p>What appears to be leak on oil tank. Stained soil. See pic 3 & 4.</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 5/30/19</p> <p>No containment under chemical barrel. Appears to be leaking stained soil. See pic 1 & 2</p> <p>Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 5/2/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection it was notified to me by the Highpoint Res employee that this well will be a KPK well in the near future.</p> <p>This is a summary of inspection report.</p> | medinaj | 04/30/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 685100869 | loc pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811054 |