

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2019

Submitted Date:

04/30/2019

Document Number:

696100836

FIELD INSPECTION FORM

Loc ID 310587 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		regulatory@foundationenergy.com	All Inspections
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293849	WELL	SI	01/01/2019	OW	123-26639	STATE 36-6	TA

General Comment:

This is a WELL inspection.
Well: TA
Entire battery & equipment is shut-down.
Centralized Battery serves 2 Location IDs: (330865, 310587).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Barbed wire		
Corrective Action:			Date:
Type	OTHER		
Comment:	Refer to FIR #696100834 and/or Location ID #330865 for Battery / Facility, Equipment info.		
Corrective Action:			Date:

Equipment:			corrective date
Type:	#		
Comment:	Refer to FIR #696100834 and/or Location ID #330865 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead does NOT appear plumbed to surface.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ master & casing valves.		
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS

	CENTRALIZED BATTERY		40.449980,-104.156260
Comment:	Centralized Battery serves 2 Location IDs: (330865, 310587). Refer to FIR #696100834 and/or Location ID #330865 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Paint			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 293849 Type: WELL API Number: 123-26639 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Wellhead is disconnected from flowline. Pumping unit removed from wellsite.
COGCC records indicate last prod: 10/2012.
Form 21 #401883026 shows MIT: 12/03/2018. Approval Pending.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: _____ Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:
Prior FIR:
Pit subsidence from former drill pit still visible.
This FIR:
Pit subsidence from former drill pit remains visible.
Contact COGCC Reclamation staff regarding drilling pit closure per rule 1003.d.
Original Corrective Action date: 04/10/2017
Prior CA remains applicable.

Corrective Action

Contact COGCC Reclamation staff regarding drilling pit closure per rule 1003.d.

Date: 04/10/2017

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary: On MON 04/29/2019 at approximately 14:04 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: FOUNDATION ENERGY MANAGEMENT LLC Location Name: STATE-66N61W /36SEW Location ID: 310587 Location County: Weld County, Colorado While there, I observed: Well(s) - 1: TA Entire battery & equipment is shut-down. Centralized Battery serves 2 Location IDs: (330865, 310587). Refer to FIR #696100834 and/or Location ID #330865 for Battery / Facility, Equipment info.</p> <p>Follow-up to FIR #684905260 dated 04/05/2018. ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.</p> <p>1 of 1: Corrective Actions from prior FIR appear NOT addressed. 1.) Prior FIR: Pit subsidence from former drill pit still visible. This FIR: Pit subsidence from former drill pit remains visible. Contact COGCC Reclamation staff regarding drilling pit closure per rule 1003.d. Original Corrective Action date: 04/10/2017 Prior CA remains applicable.</p>	<p>evinsb</p>	<p>04/30/2019</p>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100837	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811117