

Inspection Photos

Operator: Enduring Resources
Location/API #: 067-07650
Date: 4-22-2019



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of wattles and sediment deposition within the southeastern project area. Stormwater controls are not sufficient in this area.



Photo 3. View of the southwestern cut-slope that is not stabilized



Photo 4. View of the northwestern cut-slope that is not stabilized.



Photo 5. View of culvert inlet along the access road that is not stabilized. Runoff from the road flows into the stream and is not sufficiently managed.