

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2019

Submitted Date:

04/30/2019

Document Number:

679703903**FIELD INSPECTION FORM**Loc ID 315252 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
, Maralex	970-858-8550	aak@gvep.net	
Reid, Jordan	970-563-4000	maralextechjr@gmail.com	<a href="#">All inspections</a>
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	<a href="#">Operations Manager</a>
Thompson, Bud		BLThomps@BLM.gov	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230491	WELL	SI	01/01/2012	GW	103-08158	TRAIL CANYON-FEDERAL 1-2	SI

**General Comment:**[COGCC Inspection Report Summary.](#)[On 4/30/2019 at approximately 11:00, inspector Rick Moran, conducted a follow up inspection at Maralex Resources well Trail Canyon Federal 1-2 in Rio Blanco county.](#)[While there I conducted a follow up of:](#)

- [1\) FIR 675103155 from 12/7/2016](#)
- [2\) FIR 679702327 from 12/24/2018](#)
- [3\) FIR 679702848 from 2/1/2019](#)
- [4\) FIR 679703374 from 3/14/2019](#)
- [5\) warning latter document 401499076.](#)

[During this inspection the following possible compliance issues were observed as uncompleted :](#)

- [1\) Uncapped riser.](#)
- [2\) MIT.](#)

[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 679703903.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-858-8550

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	Riser next to well head not capped or LOTO.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	01/28/2019
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Inspected Facilities**Facility ID: 230491 Type: WELL API Number: 103-08158 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: [No current MIT on record or delinquent as required by Rule 326.](#)[Last recorded production December 2011. No MIT on file.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion channel on the north edge of the location going into the creek. At time of inspection water was flowing from a culvert under Rio Blanco county road 27, across the edge of the location, into the channel, then into the creek.

The P&A marker for well Trail Canyon 1-2A is located 11 ft from the edge of the erosion channel.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703904	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811223">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811223</a>