

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

690003470

FIELD INSPECTION FORM

Loc ID 336063 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 240132 | WELL | PA | 10/24/2018 | OW | 123-07920 | ST VRAIN LAND CO UNIT A 1 | PA |
| 286454 | WELL | SI | 10/01/2017 | OW | 123-24192 | REYNOLDS 7-23 | PA |
| 287497 | WELL | PA | 08/11/2017 | OW | 123-24350 | REYNOLDS 8-23 | PA |
| 287506 | WELL | PA | 10/25/2018 | OW | 123-24357 | REYNOLDS 24-23 | PA |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 240132 Type: WELL API Number: 123-07920 Status: PA Insp. Status: PAFacility ID: 286454 Type: WELL API Number: 123-24192 Status: SI Insp. Status: PAFacility ID: 287497 Type: WELL API Number: 123-24350 Status: PA Insp. Status: PAFacility ID: 287506 Type: WELL API Number: 123-24357 Status: PA Insp. Status: PA**COGCC Comments**

| Comment | User | Date |
|---|----------|------------|
| <p>On Wednesday, May 1, 2019 at 10:39, I, Craig Carlile conducted an on-site inspection at: 336063 Operated by: Anadarko</p> <p>While there I observed: Former Well location. All wells have been plugged. 05-123-24192 REYNOLDS 7-23 has been plugged, 6(S) document number: 401842930</p> <p>Other two wells have been plugged previously.</p> <p>Possible compliance issues observed: None: ?</p> <p>This is a summary of the inspection report.</p> | carlilec | 05/01/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 690003471 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4811697 |