

Inspection Photos

API: 05-071-06130

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 5/1/2019

Inspection Photos



Photo 1. Facing west along the main access road. There is vehicle rutting along the road causing widening of the road.

Inspection Photos



Photo 2. There are deep vehicle ruts along the road.

Inspection Photos



Photo 3. There is oily waste at the engine skid.