

Inspection Photos

API: 05-071-07437

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 5/1/2019

Inspection Photos



Photo 1. Facing west along the main access road. There is vehicle rutting along the road causing road damage. Stormwater is accumulating on the road.

Inspection Photos



Photo 2. Stormwater flowing across the road in the previous photo is eroding the side of the road.

Inspection Photos



Photo 3. Facing toward the wellhead. No location sign was present anywhere on location.

Inspection Photos



Photo 4. Unused pipe remains at the location.

Inspection Photos



Photo 5. There is oily waste in the engine skid.