

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/01/2019  
Submitted Date:  
05/01/2019  
Document Number:  
687904699

**FIELD INSPECTION FORM**

Loc ID 312017 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279488	WELL	PR	08/22/2005	GW	067-09065	FAIRFIELD FARMS 2	PR
281478	WELL	PR	05/07/2018	GW	067-09090	FAIRFIELD FARMS 4	PR

**General Comment:**

[Site inspection with photos at the end of this report.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Posted on tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on sign at entrance.		Date: _____
Corrective Action:			

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pump jack.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator, meter house and produced water tank.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Pump jack and linear rod pump.		
Corrective Action:		Date:	
Type: Flow Line	# 12		
Comment:	2-3" flowlines from wellhead to separator. 2-2" flowlines from wellhead blowdown to produced water tank. 2-2" flowlines from separator to produced water tank. 2-2" flowlines from separator dump valves to offsite produced water gathering system. 2-3" flowlines from separator to meter house. 2-4" flowlines from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	MCC for VFD electric driven motors.		

Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 279488 Type: WELL API Number: 067-09065 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing.

Corrective Action:

Date:

Facility ID: 281478 Type: WELL API Number: 067-09090 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Cut slope has many prairie dog holes.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687904700	Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812426">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812426</a>