

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

687904707**FIELD INSPECTION FORM**

Loc ID 311999 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Inspections, All | | SanJuanCOGCC@bp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 280301 | WELL | PR | 04/01/2018 | GW | 067-09075 | BUFORD WAYT A 2 | PR |
| 281959 | WELL | PR | 12/09/2005 | GW | 067-09092 | BUFORD WAYT A 4 | PR |

General Comment:

[Site inspection with photos at the end of this report.](#)

LocationOverall Good: ☒

| | | | |
|----------------------|-------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign posted at entrance. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Labels and placards posted on tank. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Contact information posted on sign at entrance.

Corrective Action:

Date: _____

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Cattle panels around wellhead and pumpjack. | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Cattle panels around separator, meter house and produced water tank. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Wellheads. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 10 | | |
| Comment: | 2-3" flowlines from wellhead to separator. 2-2" flowlines from wellhead to separator. 2-2" wellhead blowdown lines from separator to produced water tank. 2-2" flowlines from separator dump valves to offsite produced water gathering system. 2-3" flowlines from separator to meter house. 2-4" flowlines from meter house to offsite dogleg. | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------|--|-------|
| Type: Pump Jack | # 2 | |
| Comment: | 1 pumpjack, 1 linear rod pump. | |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 2 | |
| Comment: | PVC bradenhead access. | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 3 | |
| Comment: | 2 on separator stacks and 1 on produced water tank vent. | |
| Corrective Action: | | Date: |
| Type: Other | # 1 | |
| Comment: | MCC for VFD driven electric motors. | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|--------|
| PRODUCED WATER | 1 | <100 BBLs | PBV STEEL | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 280301 | Type: | WELL | API Number: | 067-09075 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 281959 | Type: | WELL | API Number: | 067-09092 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|
| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | Gravel | Pass | | | |
| Berms | Pass | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 687904708 | Location | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812431 |