

HILL RANCH 33-06V API# 05-071-07637 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 12, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401863



PHOTO 1: REPLACED THE PACKING TO ELIMINATE THE WATER LEAK. PACKINGS WERE SECURELY FASTENED.

HILL RANCH 33-06V API# 05-071-07637 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401863



PHOTO 2: REMOVED THE HOSE.

HILL RANCH 33-06V API# 05-071-07637 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401863



PHOTO 3: THE STAINED SOIL AROUND THE WELL HEAD HAS BEEN CLEANED UP.

HILL RANCH 33-06V API# 05-071-07637 & HILL RANCH 33-06-2 API# 05-071-08066 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401863



PHOTO 4: THE STAINED SOIL AROUND THE ENGINE SKIDS HAS BEEN CLEANED UP.

HILL RANCH 33-06V API# 05-071-07637 & HILL RANCH 33-06-2 API# 05-071-08066 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401863



PHOTO 5: THE STAINED SOIL AROUND THE ENGINE SKIDS HAS BEEN CLEANED UP.

HILL RANCH 33-06V API# 05-071-07637 & HILL RANCH 33-06-2 API# 05-071-08066 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 28, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401863



PHOTO 5: THE STAINED SOIL AROUND THE ENGINE SKIDS HAS BEEN CLEANED UP.