

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2019

Submitted Date:

05/01/2019

Document Number:

679703916

**FIELD INSPECTION FORM**
 Loc ID 316206 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256880	WELL	PR	08/17/2000	GW	103-10005	LOWER HORSE DRAW UNIT 2193	PR

**General Comment:**

COGCC Inspection Report Summary.

On 5/1/2019 at approximately 13:00, inspector Rick Moran, conducted a follow up inspection at Utah Gas's well Lower Horse Draw Unit 2193 in Rio Blanco county.

While there I conducted a follow up inspection of FIR document 679701922.

During this inspection all the corrective actions identified were resolved:

- 1) Unmarked deadman.

This is a summary of inspection report 679703916.

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 970-693-6021

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		39.836860,-108.931270
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity) 45 bbl

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 256880	Type: WELL	API Number: 103-10005	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well on plunger lift.			
Corrective Action:				Date:

--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679703918	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812583">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4812583</a>