

Inspection Photos
Operator: Enduring Resources
Location/API #: 067-08658
Date: 4-22-2019



Photo 1. View of the western fill slope from the northeastern edge facing southeastward.



Photo 2. View of the project area from the northwestern edge facing center. Revegetation is progressing within revegetation areas, although remains sparse at this early point in the growing season and should be monitored.