

Inspection Photos

API: 05-055-06179

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/1/2019

Inspection Photos



Photo 1. Facing south toward the access road. Vegetation has not established in this area.

Inspection Photos



Photo 2. Bare area near the west side of the location.

Inspection Photos



Photo 3. Facing east toward the location. Vegetation is well established at the location.

Inspection Photos



Photo 4. Facing south toward the location.

Inspection Photos



Photo 5. Facing west toward the location..

Inspection Photos



Photo 6. There is a Russian olive (List B noxious weed) at the south side of the location.

Inspection Photos



Photo 7. Facing toward the access road. This area needs reseeding.