

Inspection Photos

API: 05-055-06153

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/1/2019

Inspection Photos



Photo 1. Facing west along the access road. Vegetation is sparse in this area.

Inspection Photos



Photo 2. Facing west along the access road. Vegetation is sparse in this area.

Inspection Photos



Photo 3. Facing west toward the location.

Inspection Photos



Photo 4. Facing east toward the location. Vegetation is well established at the location.

Inspection Photos



Photo 5. Facing south toward the location. Vegetation is well established at the location.