

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2019

Submitted Date:

05/02/2019

Document Number:

688402081

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
456966 _____ Silver, Randy _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10580
Name of Operator: EXPEDITION WATER SOLUTIONS COLORADO LLC
Address: 2015 CLUBHOUSE DR SUITE 201
City: GREELEY State: CO Zip: 80634

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Goddard, Jim		kgoddard@expedition-water.com	
Koehler, Bob		bob.koehler@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456968	WELL	DG	12/14/2018		123-47686	EWS 6	DG

General Comment:

Inspected Facilities

Facility ID: 456968 Type: WELL API Number: 123-47686 Status: DG Insp. Status: DG

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: _____
 TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: _____
 Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: 0 Csg psi: 0 BH psi: 0

Insp. Status: Pass

Comment: UIC MIT test post drilling.
Witnessed MIT. Starting pressure's before tes,t Tbg psi 0, Csg psi 0, BH psi 0. Started test at approx 12:49 AM. Starting pressure 2206, 5 min 2200, 10 min 2194, 15 min 2191. 9 psi total loss during test.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>MIT due to post drilling operations.</u>	silverr	05/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688402085	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4813764